

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,546,799 B1
DATED : April 15, 2003
INVENTOR(S) : Benedetto Vigna et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6.

Lines 47 and 48, "said actuator means comprise at least" should read as -- said actuator comprise at least --.

Column 8.

Line 52, "to reactive the driving signal" should read as -- to receive the driving signal --.

Signed and Sealed this

Nineteenth Day of August, 2003



JAMES E. ROGAN
Director of the United States Patent and Trademark Office